



# Service Bulletin

American Honda Motor Co., Inc.

## 2001-2004 GL1800/A Trunk Opener Unit

Some customers may experience trunk or saddlebag lids not opening when the corresponding latch lever is pulled.

To correct this condition, the opener mechanism must be replaced with a new opener mechanism.

### REPAIR PROCEDURE

Follow the **Trunk Opener Unit Removal/Installation** instructions in the GL1800/A Gold Wing Service Manual.

### PARTS INFORMATION

**Opener Unit**  
P/N: 81310-MCA-A22  
H/C: 7700768

### WARRANTY INFORMATION

The normal GL1800/A warranty applies.


Follow all normal warranty procedures and guidelines.

Labor Operation: 412122  
Flat Rate Time: 0.6

### QUESTIONS

If you feel that goodwill consideration is appropriate, contact your District Service Manager or TechLine **BEFORE** starting this repair.

### PART DESCRIPTION



**CUSTOMER INFORMATION:** The information in this bulletin is intended for use *only* by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your Honda. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your Honda, or that your Honda has the condition described. To determine whether this information applies, contact an authorized Honda dealer.